

Unfilled Nail Hole Repair



APPEARANCE

Interior: The repair unit is dimpled or cracked. **Exterior:** Rust is evident in the unfilled hole.

PROBABLE CAUSE(S)

The injury was not filled with a plug or rubber fill material.

EXAMPLE PHOTO & FIGURE



ACTION

TIRE

Consult your retreader/repair person for possible warranty adjustment. Re-repair if possible, otherwise scrap the tire.

VEHICLE

None

OPERATIONS

Review repair requirements with road service vendors and monitor on the road tire service.